



位置図







間取り図



No.	写真	備考
1	 A photograph of a two-story house with a light beige facade and a dark brown roof. The house features a balcony on the second floor and a pergola structure in the foreground. The sky is overcast.	建物外観
2	 A photograph of a two-story house with a light beige facade and a dark brown gabled roof. The house has a fence in front and a green tarp covering an object on the left. The sky is overcast.	建物外観
3	 A photograph of a two-story house with a light beige facade and a dark brown gabled roof. The house has a utility pole in front and a concrete foundation. The sky is overcast.	建物外観

4	 A photograph of an entrance area. It features a sliding glass door with vertical blinds. To the right, there is a small wooden table with a water bottle and other items on it. A blue bucket and a white bucket are on the floor near the door. The walls are partially wood-paneled.	玄関
5	 A photograph of a toilet and sink area. A white toilet is positioned next to a wooden vanity unit that includes a sink and a mirror. A window is visible above the vanity. The floor is tiled.	トイレ 1F
6	 A photograph of a washbasin and dressing area. It shows a white washbasin with a mirror above it. There are wooden cabinets and a door in the background. The walls are wood-paneled.	洗面脱衣室 1F
7	 A photograph of a bathroom. It features a white bathtub with a showerhead and a shower tray. The walls are dark-colored, and there are wooden cabinets above the tub. The floor is tiled.	浴室 1F

8	 A photograph of a kitchen area. It features a long countertop with a sink, a stove, and a refrigerator. There are various items on the counter, including bottles and containers. A window is visible in the background, and the floor is made of light-colored wood.	キッチン 1F
9	 A photograph of a dining area. It shows a table with chairs, a kitchen counter, and a window. The room is well-lit, and there are various items on the table and counter.	ダイニング 1F
10	 A photograph of a living room. It features a large window with a view of trees outside. There is a sofa and a coffee table in the room. The floor is dark wood.	洋室 1F
11	 A photograph of a bedroom. It shows a bed, a desk, and a chair. There are various items on the desk and floor, including boxes and a blue basket. The room has a traditional Japanese style with a decorative ceiling.	和室 1F

12		和室 1F
13		洋室 2F
14		洋室 2F
15		洋室 2F

16	 A photograph of an empty room with light-colored walls and a wooden floor. A window with white curtains is visible, looking out onto a bright outdoor area. The room is framed by dark wood trim.	洋室 2F
17	 A photograph of a room with light-colored walls and a wooden floor. A window with white curtains is on the left. An air conditioner is mounted on the wall above the window. A wooden cabinet is visible in the corner.	洋室 2F
18	 A photograph taken from a balcony with a dark railing. The view shows a large green field, a white car, and some buildings in the distance under a clear sky.	バルコニー 2F
19	 A photograph of a bathroom area. A white toilet is in the center, and a wooden vanity with a sink is on the right. The walls are light-colored, and the floor is wood.	トイレ 2F

20



庭